

NAVSHIPREPFAC YOKOSUKA
LOCAL STANDARD ITEM

FY-02

ITEM NO: 099-92YO
DATE: 01 JUL 2000
CATEGORY: II

1. SCOPE:

1.1 Title: Resilient Mount; install

2. REFERENCES:

- a. NAVSHIPREPFAC Yokosuka Local Standard Items
- b. Equipment Instruction Manual
- c. S9073-A2-HBK-010, U.S. Navy Resilient Mount Handbook

3. REQUIREMENTS:

3.1 Notify NAVSHIPREPFAC of the presence of heavily misloaded or deformed mounts prior to mount removal.

3.2 Remove resilient mount assemblies, using 2.b and 2.c for guidance.

3.2.1 Inspect each equipment foundation for structural integrity, deterioration, pitting, cracks, and areas of damage or distortion.

3.2.1.1 Submit four legible copies of a report listing results of the requirements of 3.2.1 to NAVSHIPREPFAC within five working days after equipment removal.

3.2.2 Accomplish the requirements of 099-32YO of 2.a for each foundation of the removed assemblies.

3.3 Assemble, install, load, and adjust new resilient mount assemblies including load bolts, foundation bolts, nuts, and snubbers in accordance with 2.c.

3.3.1 Stamp the installation date on each resilient mount flange adjacent to the identification date. The date shall be visible and legible when the mount is installed with 1/8-inch minimum lettering size.

4. NOTES:

4.1 Equipment Instruction Manual and drawings referenced in the invoking Work Item may identify mount designation and loading requirements.

4.2 Does not include Ship's Service Diesel Generator (SSDG) and turbine enclosure mounts.